

For questions 43 through 50, unless otherwise stated, assume Champion Division, how many points do you deduct for the following items? (See Ch. VI, Judges' Guide for Scoring Non-authenticity and Score Sheet #1 Operation Verification).

43. Four wrong diameter tires and four wrong diameter wheels must receive:
- a) A deduction of 32 points because all are non-authentic.
 - b) Wrong diameter wheels must receive both a tire (2.0 points ea.) deduction, plus a wheel (6.0 points ea.) for a total of 8.0 points for each affected tire/wheel combination, with a maximum 28.0 points total deduction.
 - c) 8 points total deduction.

Ch. VI, Table F, lines 48 and 61, Page VI-7, F, Note n4, Page VI-13

44. What is the deduction for a non-functioning, missing or non-authentic four-way flasher system?
- a) No deduction
 - b) 2.0 points
 - c) 1 point for each bulb

Ch. VI, Line 19, Page VI-14

45. What is the deduction for a Champion Division Entry whose spare wheel is determined to be the wrong size or type; in consultation with the Exterior Judge, it is confirmed to match the exterior wheels; it must be given a deduction of: ___ points.
- a) 2
 - b) 4
 - c) 6

Ch. VI, Table H, Line 18, Page VI-17

46. A 1964 E-Type Champion Division Entry has the wrong cam covers and a wrong voltage regulator. Deduct: _____ each for the cam covers x 2 = _____ + _____ for the wrong regulator, for a total of _____.
- a) 1 point times 2 cam covers = 2 points + 5.0 points for the regulator = 7 points
 - b) 4 points times 2 cam covers = 8 points + 4.0 points = 12 points
 - c) 2 points times 2 cam covers = 4 points + 4.0 points = 8 points

Ch. VI, Line 14, Page VI-19 and Line 71, VI-20

47. What is the deduction for a standard XK150 (not an "S" model) that has either a **3.4L or 3.8L XK** engine with a gold cylinder head? ___ points.
- a) 1
 - b) 2
 - c) 4

Ch. VI, I Line 20, Page VI-19 and the Cylinder Head Color Table on Page VI-21

48. What is the mandatory deduction for non-authentic exhaust manifolds on an XK engine?
- a) 1 point each for a total of 2 points
 - b) 2 points each for a total of 4 points
 - c) 4 points each for a total of 8 points as XK engines have two exhaust manifolds

Ch. VI, Table I, Line 28, Page VI-19

49. An engine compartment has 15 wrong hose clamps. What is the deduction per clamp? _____ point(s); the maximum deduction for wrong hose clamps is _____ points.
- a) 1 point each, maximum of 10 points
 - b) 2 points each, maximum of 20 points
 - c) 4 points each, maximum of 30 points

Ch. VI, I, Line 41, Page VI-20

50. In Champion Division, a non-authentic oversized extra-core radiator must receive a deduction of _____ points?
- a) 8
 - b) 2
 - c) 4

Ch. VI, I, Line 53, Page VI-20